

# **RO19295 Flamebuster Xtreme Nordic Trousers**



# Reflective elements



PROTECTION LEVEL ARC 2
9.6 cal/m <sup>2</sup>
Above shown is the ERTSO value

## **EN SAFETY STANDARDS**



EN 1149-5:2008





A1 Class 1

EN ISO 13688:2013

EN ISO 11611:2007





EN ISO 11612:2008 A1 A2 B1 C1 D0 E1 F1

IEC 61482-2:2009 EBT50 9.6 cal/cm2 Class 1

EN 13034:2005 A1:2009 Type 6

Available colours		
Navy Red Orange	Royal	
Product code	Sizing	
R019295	UK30 - UK50	

**QUICK DETAIL OVERVIEW** 

Fabric weight

Trousers:

#### Inside leg length

310 g/m<sup>2</sup> Short: 29″ Regular: 31"

Tall:  $33^{\prime\prime}$  (standard size)

This garment is mostly used in > Utilities / Petrochemicals / Renewables / Industrial electrical



# RO19295 Flamebuster Xtreme Nordic Trousers

### **FEATURES & BENEFITS**

Flame retardant retroreflective tape > Stay visible in any situation
2 Side pockets with trouser access > Easy to reach
2 Back pockets > Double the storage space
Knee pad pockets > Place for your kneepads
Rule pocket on right leg > Always space for a ruler

## **KEY FEATURES**



#### **Related products**



**RO19190 - Xtreme Nordic Jacket** Flamebuster Xtreme Nordic Jacket.

## **FABRIC INFORMATION**

#### **Fabric composition**

Xtreme 310 - 60% modacrylic / 33% cotton / 5% nylon / 2% antistatic

Fabric	weight
--------	--------

310 g/m<sup>2</sup>

2

# Inherent

**FR Fabric Type** 

#### Logo

OEKO-TEX® CONFIDENCE IN TEXTILES STANDARD 100


AS/NZ 4399:1996 Sun protective clothing UPF 50+ (Excellent Protection)

Please visit www.roots-original.com/certificates to download all relevant certificates.

SHWO 093194 TESTEX

Oeko-Tex Standard 100

Additional certification



#### **Product care instructions**

To preserve the fabrics strength and protective capacity, we strongly advice to follow our detailed care instructions.

- 1. Always launder with coverall zippers closed.
- 2. Remove all tools from pockets
- 3. Rinse properly after wash.
- 4. Never wash flame retardant clothing with detergents containing bleach.
- 5. After washing, tumble dry at 50°C to avoid excessive shrinkage.
- 6. Do not iron directly over heat seal logos.

# \* 7H: @

Whenever in doubt or in need of advice, ask your dry cleaner or contact us. We are here to help or visit www.roots-original.com/product-care



## YOUR ARC FLASH PROTECTION SPECIALISTS

Get in contact, we'd love to help you!

Give us a call on +31 (0)10 2955 955 or drop us a message at: info@roots-original.com